

## GENESIS QUAD PRESS 52

CASA HERRERA HAS BEEN IN RESEARCH & DEVELOPMENT ON ITS 52 X 52 FLOUR TORTILLA PRESS FOR OVER TWO YEARS. EXTENSIVE ANALYSIS OF STRESS AND DEFLECTION HAVE BEEN DONE BY PROFESSIONAL ENGINEERS. THIS ANALYSIS REQUIRED NUMEROUS DESIGN CHANGES TO MINIMIZE STRESS AND DEFLECTION THUS ASSURING THE FLATEST PLATEN SURFACES CURRENTLY AVAILABLE IN THE INDUSTRY. FLAT PLATENS MAKE ROUND, EVEN SIZED TORTILLAS.

## CAPACITY (SINGLE DROP)

- 3.240 to 3.600 Dz/H of 6" tortillas.
- 2,160 to 2400 Dz/H of 8" tortillas.
- 1,440 to 1,600 Dz/H of 10" tortillas.
- 810 to 900 Dz/H of 12" to 14" tortillas. Production can be doubled using a double drop system.

  \*\* Maximizer needed to achive the higher capacity.

## HYDRAULICS

when running some of those difficult to manage recipies such as low carb.

The system has a separate pump to handle the Kidney Loop to filter and cool the hydraulic fluid any time the press is powered up. It also continuously monitors particle size of the hydraulic fluid to alert the operator of any potential issues. The system has state of the art hydraulic control for speed and accuracy.

Another unique feature of the new design, is the fact that it uses four cylinders to press the tortillas.


The hydraulic control allows the operator to adjust each cylinder independently up to five thousandths of an inch while the press is in operation.

## CONTROLS

Casa Herrera has recently moved to the new Automation Direct Productivity PAC 3000 series micro processor. This is one of the first combinations of a PLC and a PC in one package. It is extremely fast and can do a scan of a complete production line, for validating operating parameters, in less than one millisecond. This informs and alerts the operator of any issues while they are correctable and not catastrophic. Casa Herrera typically continuously monitors over 100 critical points on the complete line during production. This processor allows us to accomplish that monitoring with ease in less than .6 miliseconds.

The diagnostic features of the new system are a real asset to the maintenance staff in charge of maintaining the system. There are screens on the I/O modules that show status on a continuous basis. They are also integrated into the touch screen. The modules are fused and can show if a fuse is blown on which module as well as its location and many other features. We were extremely pleased by the features of the new system and to be able to offer them all to you.





We are constantly working to develop and improve our products to better serve your growing needs.





2655 North Pine Street, Pomona, California 91767 Telephone: 909.392.3930 Fax: 909.392.0231

WWW.CASAHERRERA.COM